






OSPprobe.PrjPcb


## Ports



## Debug connectors




## UI LED






## ESP32 S3 supermini connectors




## 3V3/5V Level Shifter




## UI Buttons




## OLED Connectors



For Physical support



Remove R8 and R9 (both 0Ω)



Cross connect

